



Section 1: Background Data subwatershed: FB Outfall ID: PB-10 Date & Time: 4125107 Form completed by: MAK 60° Rainfall (in.): Last 24 hours: Last 48 hours: Temperature (°F): Camera: Photo #s: (FB-016) DIAMETER (IN) **MATERIAL FLOW DESCRIPTION LAND USE IN AREA** Diameter: ☐ RCP ☐ CMP Depth: in. ☐ Industrial Trickle Open Space 18 in. ☐ PVC ☐ HDPE Width: in. ☐ Moderate Urban Residential ☐ Institutional ☐ Steel Corr. Plastic ☐ Substantial Other: ____ Other: ☐ No Flow ☐ Commercial Notes (e.g.., Access to outfall, distance and bearing if necessary, unable to locate, etc): From dutention basin . Flaced end BIR 0" rain 48 hrs **CHECK if INDICATOR** DESCRIPTION **RELATIVE SEVERITY INDEX (1-3)** Present ☐ Rancid/sour ☐ Sewage ☐ 3 – Noticeable from a ☐ Petroleum/gas Odor ☐ 1 – Faint ☐ 2 – Easily detected distance ☐ Sulfide Other: ☐ Clear Brown ☐ 1 – Faint colors ☐ Yellow ☐ Gray ☐ 2 – Clearly visible in \square 3 – Clearly visible in outfall Color \Box in sample Green ☐ Orange sample bottle bottle Red Other: \square 1 – Slight Turbidity П \square 2 – Cloudy See severity ☐ 3 – Opaque cloudiness Sewage (Toilet Paper, etc.) Floatables \square 2 – Some; indications of 3 - Some; origin clear (e.g., Suds -Does Not ☐ 1 – Few/slight; П origin (e.g., possible obvious oil sheen, suds, or Include origin not obvious Petroleum (oil sheen) suds or oil sheen) floating sanitary materials) Trash!! Other: **CHECK if** INDICATOR DESCRIPTION **COMMENTS** Present Spalling, Cracking or Chipping Peeling Paint Outfall Damage Corrosion Deposits/Stains Oily ☐ Flow Line ☐ Paint Other: Abnormal ☐ Excessive ☐ Inhibited Vegetation ☐ Odors ☐ Colors ☐ Floatables Oil Sheen Poor pool quality Suds ☐ Excessive Algae Other:

Pipe benthic

growth

Brown

☐ Orange

☐ Green

Other: