



Section 1: Background Data FB Subwatershed: Outfall ID: FB-18 Jate & Time: 513167 Form completed by: SCS MAK Rainfall (in.): Last 24 hours: 0 Last 48 hours: . \ 5 Temperature (°F): 3.4 Photo #s: (FB-018) Camera: disposuble 3.04 LAND USE IN AREA **DIAMETER (IN)** MATERIAL **FLOW DESCRIPTION** Diameter: □ СМР Open Space RCP RCP Depth: in. ☐ Trickle ☐ PVC ☐ HDPE ☐ Institutional Width: \_\_\_\_ in. ☐ Moderate Urban Residential 🗖 Corr. Plastic ☐ Steel ☐ Substantial ☐ Suburban Residential Other: \_\_ Other: No Flow ☐ Commercial Notes (e.g., Access to outfall, distance and bearing if necessary, unable to locate, etc): · Flared end . From MH BIR Total O"rain 48 hrs 4:00 **CHECK if RELATIVE SEVERITY INDEX (1-3)** DICATOR DESCRIPTION **Present** ☐ Rancid/sour ☐ Sewage ☐ 3 – Noticeable from a Petroleum/gas Odor ☐ 1 - Faint ☐ 2 – Easily detected distance ☐ Sulfide Other: ☐ Clear ☐ Brown ☐ 1 – Faint colors ☐ Gray ☐ Yellow ☐ 2 – Clearly visible in ☐ 3 – Clearly visible in outfall Color in sample ☐ Green ☐ Orange sample bottle flow bottle Red Other: ☐ 1 – Slight Turbidity See severity 2 – Cloudy ☐ 3 – Opaque cloudiness ☐ Sewage (Toilet Paper, etc.) Floatables  $\square$  2 – Some; indications of 3 - Some; origin clear (e.g., ☐ Suds -Does Not ☐ 1 – Few/slight; origin (e.g., possible obvious oil sheen, suds, or Include origin not obvious Petroleum (oil sheen) suds or oil sheen) floating sanitary materials) Trash!! Other: **CHECK if INDICATOR** DESCRIPTION COMMENTS **Present** Spalling, Cracking or Chipping Peeling Paint Outfall Damage ☐ Flow Line Oily ☐ Paint Other: Deposits/Stains Abnormal ☐ Excessive ☐ Inhibited Vegetation Odors Oil Sheen ☐ Colors ☐ Floatables Poor pool quality ☐ Suds ☐ Excessive Algae Other:

Other:

Green

Pipe benthic

growth

☐ Brown

☐ Orange