OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

GOA COA

Section 1: Ba	ckground l	Data				· ·	
Subwatershed:	7 2	>	Outfall ID: $JB-7$				
le & Time: 1:14 4/25/07			Form completed by: MAK				
Temperature (°F)	8000	,	Rainfall (in.): Last 24 hours: C Last 48 hours: C				
Camera: 2	-018		Photo #s:	Photo #s: (JB-607)			
DIAMETER (IN)	MATERIAL	FLOW	DESCRIPTION	ON LAI	ND USE IN AREA	
Diameter:	□ RC	СР 🙇 СМР	Depth: in.	☐ Trickle	M Industrial	☐ Open Space	
in.	□ PV	C HDPE	Width: in.	☐ Moderate	Urban Residential	l Institutional	
•	☐ Ste	eel Corr. Plastic		■ Substantial	☐ Suburban Resider	ntial Other:	
	☐ Ot	her:		☐ No Flow	☐ Commercial		
· Colver,	, 0 07 4	~ (0) Out 10 -10 A	irectly into it				
DICATOR	CHECK if Present	DESCRIP	3,46 p		rain 48 b		
Odor		Sewage Rar Petroleum/gas Sulfide Oth	neid/sour	Faint	2 – Easily detected	3 – Noticeable from a distance	
Color		☐ Clear ☐ Bro ☐ Gray ☐ Yel ☐ Green ☐ Ora ☐ Red ☐ Othor	llow in h		2 – Clearly visible in mple bottle	3 – Clearly visible in outfall flow	
Turbidity		See sever	rity		2 – Cloudy	3 – Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds Petroleum (oil sheer Other:	□1-	Few/slight; not obvious	2 – Some; indications of origin (e.g., possible suds or oil sheen)	3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)	
	CHEC	Cif					
Outfall Damage	Prese		DESCRIPTION COMMENTS "acking or Chipping Peeling Paint				
Outfall Damage		Corrosion					
Abnormal							
Vegetation		Odors	Odors Colors Oil Sheen Suds Excessive Algae Other:				
Pipe benthic			☐ Orange ☐ Green ☐ Other:				