OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

ection 1: Background Data subwatershed: Outfall ID: 18-15 MAK Date & Time: Form completed by: 4/25/07 17:58 Rainfall (in.): Last 24 hours: Last 48 hours: Temperature (°F): 60 Camera: Photo #s: (JB-615) **DIAMETER (IN) MATERIAL FLOW DESCRIPTION LAND USE IN AREA** Diameter: $\prod RCP$ CMP Depth: in. Trickle ™ Industrial Open Space 36 in. □ PVC ☐ HDPE Urban Residential ☐ Institutional Width: in. ☐ Moderate Corr. Plastic ☐ Substantial ☐ Steel Suburban Residential Other: Other: No Flow ☐ Commercial Notes (e.g., Access to outfall, distance and bearing if necessary, unable to locate, etc): ·Flared end · From CB · Partially submerged 0" rain 48 ms BTR **CHECK if INDICATOR** DESCRIPTION **RELATIVE SEVERITY INDEX (1-3) Present** ☐ Sewage ☐ Rancid/sour ☐ 3 – Noticeable from a Petroleum/gas ☐ 1 - Faint ☐ 2 – Easily detected Odor distance ☐ Sulfide Other: ☐ Brown ☐ Clear \square 1 – Faint colors Gray ☐ Yellow ☐ 2 – Clearly visible in ☐ 3 – Clearly visible in outfall Color in sample ☐ Green ☐ Orange sample bottle flow bottle Red Other: ☐ 1 - Slight \square 2 – Cloudy ☐ 3 – Opaque Turbidity See severity cloudiness Sewage (Toilet Paper, etc.) Floatables \square 2 – Some; indications of 3 - Some; origin clear (e.g., Suds -Does Not \square 1 – Few/slight; obvious oil sheen, suds, or origin (e.g., possible Include origin not obvious Petroleum (oil sheen) suds or oil sheen) floating sanitary materials) Trash!! Other: **CHECK if INDICATOR** DESCRIPTION **COMMENTS** Present Spalling, Cracking or Chipping ☐ Peeling Paint Outfall Damage Corrosion Deposits/Stains Oily ☐ Flow Line ☐ Paint Other: Abnormal ☐ Excessive ☐ Inhibited Vegetation Oil Sheen ☐ Odors Colors ☐ Floatables Poor pool quality ☐ Suds

☐ Excessive Algae

Green

☐ Orange

Pipe benthic

growth

☐ Brown

Other:

Other: