



Section 1: Background Data Subwatershed: Outfall ID: L= te & Time: Form completed by: 4125107 MAK Temperature (°F): Rainfall (in.): Last 24 hours: / Last 48 hours: 60° Camera: Photo #s: (L -00 1) **MATERIAL FLOW DIAMETER (IN) DESCRIPTION LAND USE IN AREA** Diameter: **№** RCP П СМР Depth: in. ☐ Trickle ☐ Industrial Open Space 18 in. □ PVC ☐ HDPE Width: in. ☐ Moderate ☐ Urban Residential ☐ Institutional Other: __ ☐ Steel Corr. Plastic ☐ Substantial M Suburban Residential Other: No Flow ☐ Commercial Notes (e.g.., Access to outfall, distance and bearing if necessary, unable to locate, etc): . Flored end · From OB MH BTR rain 48 hrs **CHECK if DICATOR** DESCRIPTION **RELATIVE SEVERITY INDEX (1-3)** Present □ Sewage ☐ Rancid/sour ☐ 3 – Noticeable from a Petroleum/gas Odor ☐ 1 – Faint 2 – Easily detected distance ☐ Sulfide Other: ☐ Clear ☐ Brown ☐ 1 – Faint colors Gray Yellow 2 – Clearly visible in \square 3 – Clearly visible in outfall Color in sample Green ☐ Orange sample bottle flow bottle Red Other: ☐ 1 – Slight Turbidity \square 2 – Cloudy See severity ☐ 3 – Opaque cloudiness ☐ Sewage (Toilet Paper, etc.) Floatables \square 2 – Some; indications of 3 - Some; origin clear (e.g., Suds -Does Not ☐ 1 – Few/slight; origin (e.g., possible obvious oil sheen, suds, or Include origin not obvious Petroleum (oil sheen) suds or oil sheen) floating sanitary materials) Trash!! Other: **CHECK if INDICATOR** DESCRIPTION COMMENTS Present Spalling, Cracking or Chipping Peeling Paint Outfall Damage Corrosion Deposits/Stains Oily ☐ Flow Line ☐ Paint Other: Abnormal Excessive Inhibited Vegetation Oil Sheen Odors ☐ Colors ☐ Floatables or pool quality ☐ Suds ☐ Excessive Algae Other: Pipe benthic ☐ Brown ☐ Orange Green Other:

growth