



Section 1: Background Data Subwatershed: mR Outfall ID: Mrz-T Form completed by: 5 < 5 / MAS_ate & Time: 9:40 519107 Rainfall (in.): Last 24 hours: Last 48 hours: 0 Temperature (°F): 3632 (MR-005) Photo #s: Camera: MATERIAL **FLOW DESCRIPTION** DIAMETER (IN) **LAND USE IN AREA** RCP Depth: ____ in. Diameter: ☐ CMP ☐ Industrial ☐ Trickle Open Space □ PVC ☐ HDPE Width: ____ in. ☐ Moderate Urban Residential ☐ Institutional Suburban Residential ☐ Substantial ☐ Steel Corr. Plastic Other: No Flow ☐ Commercial Other: Notes (e.g., Access to outfall, distance and bearing if necessary, unable to locate, etc): - yard debris slowly impeding Strennet - large stones in flowpath **CHECK if** DICATOR DESCRIPTION **RELATIVE SEVERITY INDEX (1-3)** Present Rancid/sour ☐ Sewage \square 3 – Noticeable from a Petroleum/gas Odor □ 1 – Faint ☐ 2 – Easily detected distance ☐ Sulfide Other: Clear ☐ Brown ☐ 1 – Faint colors ☐ Yellow ☐ 2 – Clearly visible in ☐ Gray \square 3 – Clearly visible in outfall Color in sample ☐ Green ☐ Orange sample bottle bottle Red Other: ☐ 1 – Slight Turbidity See severity \square 2 – Cloudy ☐ 3 – Opaque cloudiness Sewage (Toilet Paper, etc.) Floatables \square 2 – Some; indications of 3 - Some; origin clear (e.g., Suds ☐ 1 – Few/slight; -Does Not obvious oil sheen, suds, or origin (e.g., possible Include origin not obvious Petroleum (oil sheen) suds or oil sheen) floating sanitary materials) Trash!! Other:

INDICATOR	CHECK if Present	DESCRIPTION	COMMENTS
Outfall Damage		Spalling, Cracking or Chipping Peeling Paint Corrosion	
Deposits/Stains	n.	Oily Flow Line Paint Other:	
Abnormal Vegetation	_D/	☐ Excessive ☐ Inhibited	Some moss present
Poor pool quality		☐ Odors ☐ Colors ☐ Floatables ☐ Oil Sheen ☐ Suds ☐ Excessive Algae ☐ Other:	
Pipe benthic growth		☐ Brown ☐ Orange ☐ Green ☐ Other:	