## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET



Section 1: Background Data m20-2 Outfall ID: pwatershed: MRD 1603 Date & Time: Scs + MAK Form completed by: C Last 48 hours: Rainfall (in.): Last 24 hours: Temperature (°F): 0170 (MRD-002) Photo #s: Camera: KODAK MATERIAL FLOW DIAMETER (IN) **DESCRIPTION** LAND USE IN AREA Diameter: RCP ☐ CMP Depth: in. ☐ Trickle ☐ Industrial Open Space ☐ PVC Width: \_\_\_\_ in. ☐ HDPE ☐ Moderate Urban Residential ☐ Institutional ☐ Suburban Residential ☐ Steel ☐ Substantial Other: \_\_\_ undlimate ( ☐ Commercial Other: Notes (e.g.., origin of outfall, if known): fully submerged Hewwall LB 12-3/4 Full Sediment. **CHECK if INDICATOR DESCRIPTION RELATIVE SEVERITY INDEX (1-3)** Present ☐ Rancid/sour ☐ Sewage  $\square$  3 – Noticeable from a Petroleum/gas □ 1 – Faint ☐ 2 – Easily detected Odor distance ☐ Sulfide Other: ☐ Brown ☐ Yellow Clear ☐ 1 – Faint colors ☐ Gray  $\square$  2 – Clearly visible in  $\square$  3 – Clearly visible in outfall Color in sample Green ☐ Orange sample bottle bottle Red Other: ☐ 1 – Slight 2 – Cloudy Turbidity See severity 3 - Opaque cloudiness Sewage (Toilet Paper, etc.) Floatables Suds  $\square$  2 – Some; indications of 3 - Some; origin clear (e.g., ☐ 1 – Few/slight; -Does Not origin (e.g., possible obvious oil sheen, suds, or Include origin not obvious Petroleum (oil sheen) suds or oil sheen) floating sanitary materials) Trash!! Other:

INDICATOR	CHECK if Present	DESCRIPTION	COMMENTS
Outfall Damage		Spalling, Cracking or Chipping Peeling Paint Corrosion	1
Deposits/Stains		Oily Flow Line Paint Other:	
Abnormal Vegetation	5	☐ Excessive ☐ Inhibited	50 me m 0 55
Poor pool quality		☐ Odors ☐ Colors ☐ Floatables ☐ Oil Sheen ☐ Suds ☐ Excessive Algae ☐ Other:	
Pipe benthic growth		☐ Brown ☐ Orange ☐ Green ☐ Other:	