OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Background Data PB-94 Subwatershed: Outfall ID: 513167 Jate & Time: Form completed by: SCS 12:00 MAK Last 48 hours: -15 Rainfall (in.): Last 24 hours: Temperature (°F): Camera: Photo #s: disposable 325 PB-094 **FLOW DIAMETER (IN) MATERIAL DESCRIPTION LAND USE IN AREA** Diameter: ☐ RCP ☐ CMP Depth: in. ☐ Trickle ☐ Industrial Open Space 18 _ in. \square PVC ☐ HDPE Width: in. ☐ Moderate Urban Residential Institutional ☐ Steel 🔀 Corr. Plastic Substantial ☐ Suburban Residential Other: ____ Other: 🔀 No Flow ☐ Commercial Notes (e.g.., Access to outfall, distance and bearing if necessary, unable to locate, etc): · submerged · Full of sediment rein 48ho 11:10 m CHECK if **IDICATOR** DESCRIPTION **RELATIVE SEVERITY INDEX (1-3) Present** ☐ Sewage ☐ Rancid/sour ☐ 3 – Noticeable from a ☐ Petroleum/gas Odor ☐ 1 – Faint ☐ 2 – Easily detected distance ☐ Sulfide Other: ☐ Clear ☐ Brown ☐ 1 – Faint colors ☐ Yellow \square 2 – Clearly visible in ☐ 3 – Clearly visible in outfall Gray in sample Color Green Orange sample bottle bottle Red Other: ☐ 1 - Slight Turbidity See severity \square 2 – Cloudy 3 – Opaque cloudiness Sewage (Toilet Paper, etc.) Floatables \square 2 – Some; indications of 3 - Some; origin clear (e.g., Suds -Does Not \square 1 – Few/slight; obvious oil sheen, suds, or origin (e.g., possible Include origin not obvious Petroleum (oil sheen) suds or oil sheen) floating sanitary materials) Trash!! Other: **CHECK if INDICATOR DESCRIPTION** COMMENTS Present Spalling, Cracking or Chipping Peeling Paint Outfall Damage Corrosion Deposits/Stains Oily ☐ Flow Line Paint Other: Abnormal П □ Excessive ☐ Inhibited Vegetation Oil Sheen ☐ Odors ☐ Colors ☐ Floatables Poor pool quality ☐ Suds ☐ Excessive Algae Other: Pipe benthic Other: Brown ☐ Orange Green

growth