Kon

OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

ection 1: Background Data Outfall ID: Subwatershed: NB WB-99 Form completed by: Date & Time: 4/25/07 MAK Rainfall (in.): Last 24 hours: Last 48 hours: Temperature (°F): 59° Photo #s: 1WR-099) Camera: 1,04 **MATERIAL FLOW DESCRIPTION LAND USE IN AREA** DIAMETER (IN) □ RCP □ СМР Trickle ☐ Industrial Open Space Diameter: Depth: in. 29 $\prod PVC$ ☐ HDPE Width: in. ☐ Moderate Urban Residential ☐ Institutional in. ☐ Steel Corr. Plastic ☐ Substantial 🕅 Suburban Residential Other: _____ Other: ☐ No Flow ☐ Commercial Notes (e.g., Access to outfall, distance and bearing if necessary, unable to locate, etc): · From CB ·Between houses ·Half submerged BTR 9/2/08 O'rain 48 hrs 9:25 an **CHECK if INDICATOR RELATIVE SEVERITY INDEX (1-3)** DESCRIPTION **Present** ☐ Sewage ☐ Rancid/sour \square 3 – Noticeable from a Petroleum/gas □ 1 – Faint ☐ 2 – Easily detected Odor distance ☐ Sulfide Other: Clear ☐ Brown ☐ 1 – Faint colors ☐ Yellow 2 – Clearly visible in ☐ 3 – Clearly visible in outfall Gray in sample Color ☐ Green ☐ Orange sample bottle bottle Red Other: ☐ 1 – Slight 2 – Cloudy 3 – Opaque Turbidity See severity cloudiness Sewage (Toilet Paper, etc.) Floatables \square 2 – Some; indications of 3 - Some; origin clear (e.g., ☐ Suds ☐ 1 – Few/slight; -Does Not obvious oil sheen, suds, or origin (e.g., possible origin not obvious Include Petroleum (oil sheen) suds or oil sheen) floating sanitary materials) Trash!! Other: **CHECK if INDICATOR DESCRIPTION COMMENTS** Present Spalling, Cracking or Chipping Peeling Paint Outfall Damage Corrosion Deposits/Stains Oily ☐ Flow Line Paint Other: Abnormal ☐ Excessive Inhibited Vegetation ☐ Odors □ Colors ☐ Floatables Oil Sheen Poor pool quality Suds Excessive Algae Other:

Other:

Green

Pipe benthic

growth

☐ Brown

☐ Orange