

Property Location: 167 CANTERBURY CR															MAP ID: 19/ 51/ 10/ /															Bldg Name:															State Use: 101																																												
Vision ID: 6711															Account #6828															Bldg #: 1 of 1															Sec #: 1 of 1															Card 1 of 1															Print Date: 12/07/2016 12:55														
CURRENT OWNER															TOPO.					UTILITIES					STRT./ROAD					LOCATION					CURRENT ASSESSMENT															1006 AST LONGMEADOW, MA <																																							

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac			
Grade	B		GOOD	FBM Sqft			
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			89.97
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			339,366
AC Type	03		FULL	AYB			2014
Bedrooms	5			EYB			2014
Full Baths	2			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	2			Year Remodeled			
Total Rooms	8			Dep %			0
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	G		GOOD	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens				Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			100
Bsmt Garage				Apprais Val			339,400
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

