

VISION


CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	1.50		1 1/2 Stories	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage
Exterior Wall 2	16		STONE VENR	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			95.29
Interior Floor 2							
Heat Fuel	1		OIL				
Heat Type	1		FORCED H/A	Replace Cost			144,074
AC Type	03		FULL	AYB			1950
Bedrooms	4			EYB			1975
Full Baths	1			Dep Code			AV
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	6			Dep %			39
Bath Style	A		AVERAGE	Functional ObsInc			
Kitchen Style	A		AVERAGE	External ObsInc			5
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond			56
Bsmt Garage				Apprais Val			80,700
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

[illegible]

BUILDING SUB-AREA SUMMARY SECTION

[illegible]

<i>Ttl. Gross Liv/Lease Area:</i>	1,248	2,652	1,512	144,074
--	--------------	--------------	--------------	----------------



2006 8 31