

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		YES
Model	01		RESIDENTIAL	Central Vac	1		
Grade	C		AVERAGE	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			94.03
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			166,057
AC Type	03		FULL	AYB			2005
Bedrooms	3			EYB			2007
Full Baths	2			Dep Code			AV
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	5			Dep %			7
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond			93
Bsmt Garage				Apprais Val			154,400
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	616		18.78	11,566	
FFL	1ST FLOOR	616	616		94.03	57,922	
GAR	GARAGE	0	264		37.75	9,967	
OPF	OPEN PORCH	0	132		9.26	1,222	
SFL	2ND FLOOR	908	908		94.03	85,379	

Ttl. Gross Liv/Lease Area:		1,524	2,536	1,766	166,057		
----------------------------	--	-------	-------	-------	---------	--	--

SFL	22		
GAR			
12			12
5	1	16	
SFL	16	6	
FFL			
BMT			
SFL			
1			
2828			28
1		22	
OPF		22	
6		22	6



2007 8 18