

Print Date: 11/24/2015 15:37

# VISION

| CONSTRUCTION DETAIL |      |     |             | CONSTRUCTION DETAIL (CONTINUED) |             |     |             |         |
|---------------------|------|-----|-------------|---------------------------------|-------------|-----|-------------|---------|
| Element             | Cd.  | Ch. | Description | Element                         | Cd.         | Ch. | Description |         |
| Style               | 19   |     | RANCH       | #Heat Sys                       | 1           |     |             |         |
| Model               | 01   |     | RESIDENTIAL | Central Vac                     | 0           |     | NO          |         |
| Grade               | C    |     | AVERAGE     | FBM Sqft                        |             |     |             |         |
| Stories             | 1.00 |     | 1 Story     | Int vs Ext                      | S           |     |             |         |
| Foundation          | 1    |     | CONCRETE    | MIXED USE                       |             |     |             |         |
| Exterior Wall 1     | 4    |     | VINYL       | Code                            | Description |     | Percentage  |         |
| Exterior Wall 2     |      |     |             | 101                             | ONE FAM     |     | 100         |         |
| Roof Structure      | 1    |     | GABLE       | COST/MARKET VALUATION           |             |     |             |         |
| Roof Cover          | 1    |     | ASPHALT SH  |                                 |             |     |             |         |
| Interior Wall 1     | 2    |     | PLASTER     |                                 |             |     |             |         |
| Interior Wall 2     |      |     |             | Adj. Base Rate:                 |             |     |             | 95.70   |
| Interior Floor 1    | 3    |     | HARDWOOD    | Replace Cost                    |             |     |             | 131,114 |
| Interior Floor 2    |      |     |             | AYB                             |             |     |             | 1946    |
| Heat Fuel           | 2    |     | GAS         | EYB                             |             |     |             | 1975    |
| Heat Type           | 1    |     | FORCED H/A  | Dep Code                        |             |     |             | AV      |
| AC Type             | 01   |     | NONE        | Remodel Rating                  |             |     |             |         |
| Bedrooms            | 3    |     |             | Year Remodeled                  |             |     |             |         |
| Full Baths          | 1    |     |             | Dep %                           |             |     |             | 39      |
| Half Baths          | 0    |     |             | Functional Obslnc               |             |     |             |         |
| Extra Fixtures      | 0    |     |             | External Obslnc                 |             |     |             | 5       |
| Total Rooms         | 6    |     |             | Cost Trend Factor               |             |     |             | 1       |
| Bath Style          | A    |     | AVERAGE     | Condition                       |             |     |             |         |
| Kitchen Style       | A    |     | AVERAGE     | % Complete                      |             |     |             |         |
| Kitchens            | 1    |     |             | Overall % Cond                  |             |     |             | 56      |
| Extra Kitchens      | 0    |     |             | Apprais Val                     |             |     |             | 73,400  |
| Frame               | 1    |     | WOOD        | Dep % Ovr                       |             |     |             | 0       |
| Basement Floor      | 12   |     |             | Dep Ovr Comment                 |             |     |             |         |
| Bsmt Garage         |      |     |             | Misc Imp Ovr                    |             |     |             | 0       |
| Units               | 1    |     |             | Misc Imp Ovr Comment            |             |     |             |         |
| WS Flues            |      |     |             | Cost to Cure Ovr                |             |     |             | 0       |
| FBM Quality         |      |     |             | Cost to Cure Ovr Comment        |             |     |             |         |
| Fireplaces          | 0    |     |             |                                 |             |     |             |         |

| BUILDING SUB-AREA SUMMARY SECTION |             |             |            |           |           |                 |  |
|-----------------------------------|-------------|-------------|------------|-----------|-----------|-----------------|--|
| Code                              | Description | Living Area | Gross Area | Eff. Area | Unit Cost | Undeprec. Value |  |
| BMT                               | BASEMENT    | 0           | 960        |           | 19.14     | 18,375          |  |
| FFL                               | 1ST FLOOR   | 1,086       | 1,086      |           | 95.70     | 103,934         |  |
| GAR                               | GARAGE      | 0           | 231        |           | 38.12     | 8,805           |  |
| Ttl. Gross Liv/Lease Area:        |             | 1,086       | 2,277      | 1,370     |           | 131,114         |  |

