

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B-		GOOD (-)	FBM Sqft			
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	2		HIP				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			99.89
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			210,075
AC Type	01		NONE	AYB			2005
Bedrooms	3			EYB			2009
Full Baths	2			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	6			Dep %			5
Bath Style	G		GOOD	Functional ObsInc			
Kitchen Style	G		GOOD	External ObsInc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			95
Bsmt Garage				Apprais Val			199,600
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
11	POOL I-V	OB	Outbuilding	L	512	29.00	2005	A		GD	70	10,400

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	656		19.95	13,086
EFP	ENCL PORCH	0	168		29.73	4,995
FFL	1ST FLOOR	656	656		99.89	65,530
GAR	GARAGE	0	640		39.96	25,573
OFF	OPEN PORCH	0	132		9.84	1,299
SFL	2ND FLOOR	997	997		99.89	99,593

Ttl. Gross Liv/Lease Area:		1,653	3,249	2,103		210,075
----------------------------	--	-------	-------	-------	--	---------

