

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.75		1 3/4 Stories	Int vs Ext	S			
Foundation	2		CONC BLOCK	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	2		PLASTER					
Interior Wall 2								
Interior Floor 1	4		CARPET					
Interior Floor 2	3		HARDWOOD	Adj. Base Rate:				86.59
Heat Fuel	1		OIL	Replace Cost				168,504
Heat Type	3		FORCED H/W					
AC Type	01		NONE	AYB				1959
Bedrooms	4			EYB				1980
Full Baths	2			Dep Code				AG
Half Baths	0			Remodel Rating				
Extra Fixtures	0			Year Remodeled				
Total Rooms	8			Dep %				34
Bath Style	A		AVERAGE	Functional Obslnc				
Kitchen Style	A		AVERAGE	External Obslnc				
Kitchens	1			Cost Trend Factor				1
Extra Kitchens	0			Condition				
Frame	1		WOOD	% Complete				
Basement Floor	12			Overall % Cond				66
Bsmt Garage				Apprais Val				111,200
Units	1			Dep % Ovr				0
WS Flues				Dep Ovr Comment				
FBM Quality				Misc Imp Ovr				0
Fireplaces	1			Misc Imp Ovr Comment				
				Cost to Cure Ovr				0
				Cost to Cure Ovr Comment				

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	160	7.48	2001	A		GD	70	800

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	912		17.28	15,759	
FFL	1ST FLOOR	1,080	1,080		86.59	93,517	
TQS	3/4 STORY	684	912		64.94	59,227	

Ttl. Gross Liv/Lease Area:		1,764	2,904	1,946		168,504	
----------------------------	--	-------	-------	-------	--	---------	--

TQS	38	2	
FFL		FFL	12
BMT			
		14	14
24			14
			12
		8	
	38		

