

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	1.75		1 3/4 Stories	Int vs Ext	S		
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2	1		DRYWALL	COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		87.10	
Interior Floor 2	4		CARPET				
Heat Fuel	1		OIL				
Heat Type	3		FORCED H/W	Replace Cost		170,707	
AC Type	01		NONE	AYB		1959	
Bedrooms	4			EYB		1980	
Full Baths	2			Dep Code		AG	
Half Baths	0			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	8			Dep %		34	
Bath Style	A		AVERAGE	Functional ObsInc			
Kitchen Style	A		AVERAGE	External ObsInc			
Kitchens	1			Cost Trend Factor		1	
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond		66	
Bsmt Garage				Apprais Val		112,700	
Units	1			Dep % Ovr		0	
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr		0	
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
04	GARAGE/L			L	576	30.48	1967	A		AV	60	10,500

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	912		17.38	15,851	
FFL	1ST FLOOR	1,094	1,094		87.10	95,282	
TQS	3/4 STORY	684	912		65.32	59,573	
Ttl. Gross Liv/Lease Area:		1,778	2,918	1,960		170,707	

FFL	14	TQS	38
		FFL	
		BMT	
		2	
13		13	
	14		24
		9	
			38

