

CURRENT OWNER				TOPO.				UTILITIES				STRT./ROAD				LOCATION				CURRENT ASSESSMENT											
FEARN THOMAS R FEARN SUSAN E 52 MOORE ST EAST LONGMEADOW, MA 01028 Additional Owners:								1 TYPCL												Description		Code		Appraised Value		Assessed Value		1006 AST LONGMEADOW, M 			

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	18		SPLIT ENT	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		
Grade	C+		AVG. (+)	FBM Sqft	845		
Stories	1.00		1 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			114.74
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			185,074
AC Type	03		Full	AYB			1990
Bedrooms	4			EYB			2004
Full Baths	2			Dep Code			GV
Half Baths	1			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	6			Dep %			10
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor				Overall % Cond			90
Bsmt Garage				Apprais Val			166,600
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr			0
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

