

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	1		YES
Grade	B		GOOD	FBM Sqft	1067		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	8		BRICK VENR	Code	Description		Percentage
Exterior Wall 2	4		VINYL	101	ONE FAM		100
Roof Structure	2		HIP				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			90.44
Interior Floor 2	6		CERAMIC TL				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			387,283
AC Type	03		FULL	AYB			1996
Bedrooms	4			EYB			2004
Full Baths	3			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	3			Year Remodeled			
Total Rooms	8			Dep %			10
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	G		GOOD	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			90
Bsmt Garage				Apprais Val			348,600
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	1			Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)							
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	2,134		18.10	38,620
CFL	CATHEDRAL CE	381	381		93.06	35,454
FFL	1ST FLOOR	1,753	1,753		90.44	158,549
GAR	GARAGE	0	808		36.16	29,214
OPF	OPEN PORCH	0	104		8.70	904
PAT	PATIO	0	1,084		4.51	4,884
SFL	2ND FLOOR	1,323	1,323		90.44	119,658
Ttl. Gross Liv/Lease Area:		3,457	7,587	4,282		387,283

