

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	19		RANCH	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.00		1 STORY	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	2		PLASTER					
Interior Wall 2				Adj. Base Rate:				96.50
Interior Floor 1	3		HARDWOOD	Replace Cost AYB EYB Dep Code Remodel Rating Year Remodeled Dep % Functional Obslnc External Obslnc Cost Trend Factor Condition % Complete Overall % Cond Apprais Val Dep % Ovr Dep Ovr Comment Misc Imp Ovr Misc Imp Ovr Comment Cost to Cure Ovr Cost to Cure Ovr Comment				129,982
Interior Floor 2	4		CARPET					1956
Heat Fuel	1		OIL					1975
Heat Type	3		FORCED H/W					AV
AC Type	01		NONE					
Bedrooms	3							
Full Baths	1							
Half Baths	0							
Extra Fixtures	0							39
Total Rooms	5							
Bath Style	A		AVERAGE					
Kitchen Style	A		AVERAGE					1
Kitchens	1							
Extra Kitchens	0							
Frame	1		WOOD					61
Basement Floor	12		CONCRETE					79,300
Bsmt Garage								0
Units	1							
WS Flues								0
FBM Quality								
Fireplaces	0							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
03	GARAGE	OB	Outbuilding	L	484	28.18	1956	A		AV	60	8,200

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,096		19.28	21,133
EFP	ENCL PORCH	0	96		29.15	2,798
FFL	1ST FLOOR	1,096	1,096		96.50	105,761
OPF	OPEN PORCH	0	32		9.05	289
Ttl. Gross Liv/Lease Area:		1,096	2,320	1,347		129,982

