

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	12		MULTI-CONV	#Heat Sys	2		
Model	03		MULTI-FAMILY	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				104	TWO FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2	8		PLYWD PANL	COST/MARKET VALUATION			
Interior Floor 1	2		SOFTWOOD	Adj. Base Rate:			77.68
Interior Floor 2							
Heat Fuel	2		GAS				
Heat Type	5		STEAM	Replace Cost			192,091
AC Type	01		NONE	AYB			1930
Bedrooms	4			EYB			1998
Full Baths	2			Dep Code			VG
Half Baths	0			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	12			Dep %			16
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	2			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond			84
Bsmt Garage				Apprais Val			161,400
Units	3			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	64	7.48	1990	A		AV	60	300

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,104		15.55	17,166
FFL	1ST FLOOR	1,124	1,124		77.68	87,307
OFP	OPEN PORCH	0	40		7.77	311
SFL	2ND FLOOR	1,124	1,124		77.68	87,307
Ttl. Gross Liv/Lease Area:		2,248	3,392	2,473		192,091

