

Print Date: 12/02/2016 13:21

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	494		
Stories	1.00		1 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			108.81
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost			129,919
Heat Type	3		FORCED H/W	AYB			1960
AC Type	01		NONE	EYB			1980
Bedrooms	4			Dep Code			AG
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %			34
Total Rooms	6			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			66
Basement Floor	12		CONCRETE	Apprais Val			85,700
Bsmt Garage	1			Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality	1			Misc Imp Ovr Comment			
Fireplaces	0			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	80	7.48	2010	A		GD	70	400

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	988		21.81	21,544	
FFL	1ST FLOOR	988	988		108.81	107,504	
PAT	PATIO	0	150		5.80	870	
Ttl. Gross Liv/Lease Area:		988	2,126	1,194		129,919	

FFL	38		
BMT			
26			26
23		15	
		PAT	15
		10	10
			15

