

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B-		GOOD (-)	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			87.25
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			283,907
AC Type	03		FULL	AYB			2005
Bedrooms	4			EYB			2009
Full Baths	2			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	8			Dep %			5
Bath Style	G		GOOD	Functional ObsInc			
Kitchen Style	G		GOOD	External ObsInc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond			95
Bsmt Garage				Apprais Val			269,700
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,440		17.45	25,128
FFL	1ST FLOOR	1,440	1,440		87.25	125,638
GAR	GARAGE	0	576		34.84	20,067
HST	HALF STORY	288	576		43.62	25,128
SFL	2ND FLOOR	1,008	1,008		87.25	87,947

Ttl. Gross Liv/Lease Area:		2,736	5,040	3,254		283,907
----------------------------	--	-------	-------	-------	--	---------

