

**Print Date: 11/30/2016 16:53**

[illegible]

| CONSTRUCTION DETAIL |      |     |               | CONSTRUCTION DETAIL (CONTINUED) |             |     |             |
|---------------------|------|-----|---------------|---------------------------------|-------------|-----|-------------|
| Element             | Cd.  | Ch. | Description   | Element                         | Cd.         | Ch. | Description |
| Style               | 05   |     | CAPE          | #Heat Sys                       | 1           |     |             |
| Model               | 01   |     | RESIDENTIAL   | Central Vac                     | 0           |     | NO          |
| Grade               | C    |     | AVERAGE       | FBM Sqft                        |             |     |             |
| Stories             | 1.50 |     | 1 1/2 STORIES | Int vs Ext                      | S           |     | SAME        |
| Foundation          | 2    |     | CONC BLOCK    | MIXED USE                       |             |     |             |
| Exterior Wall 1     | 1    |     | WOOD SHING    | Code                            | Description |     | Percentage  |
| Exterior Wall 2     |      |     |               | 101                             | ONE FAM     |     | 100         |
| Roof Structure      | 1    |     | GABLE         |                                 |             |     |             |
| Roof Cover          | 1    |     | ASPHALT SH    |                                 |             |     |             |
| Interior Wall 1     | 1    |     | DRYWALL       |                                 |             |     |             |
| Interior Wall 2     |      |     |               | COST/MARKET VALUATION           |             |     |             |
| Interior Floor 1    | 3    |     | HARDWOOD      | Adj. Base Rate:                 |             |     | 86.69       |
| Interior Floor 2    | 4    |     | CARPET        |                                 |             |     |             |
| Heat Fuel           | 2    |     | GAS           |                                 |             |     |             |
| Heat Type           | 1    |     | FORCED H/A    | Replace Cost                    |             |     | 176,333     |
| AC Type             | 01   |     | NONE          | AYB                             |             |     | 1952        |
| Bedrooms            | 4    |     |               | EYB                             |             |     | 1980        |
| Full Baths          | 2    |     |               | Dep Code                        |             |     | AG          |
| Half Baths          | 0    |     |               | Remodel Rating                  |             |     |             |
| Extra Fixtures      | 1    |     |               | Year Remodeled                  |             |     |             |
| Total Rooms         | 8    |     |               | Dep %                           |             |     | 34          |
| Bath Style          | A    |     | AVERAGE       | Functional Obslnc               |             |     |             |
| Kitchen Style       | A    |     | AVERAGE       | External Obslnc                 |             |     |             |
| Kitchens            | 1    |     |               | Cost Trend Factor               |             |     | 1           |
| Extra Kitchens      | 0    |     |               | Condition                       |             |     |             |
| Frame               | 1    |     | WOOD          | % Complete                      |             |     |             |
| Basement Floor      | 12   |     | CONCRETE      | Overall % Cond                  |             |     | 66          |
| Bsmt Garage         |      |     |               | Apprais Val                     |             |     | 116,400     |
| Units               | 1    |     |               | Dep % Ovr                       |             |     | 0           |
| WS Flues            |      |     |               | Dep Ovr Comment                 |             |     |             |
| FBM Quality         |      |     |               | Misc Imp Ovr                    |             |     | 0           |
| Fireplaces          | 1    |     |               | Misc Imp Ovr Comment            |             |     |             |
|                     |      |     |               | Cost to Cure Ovr                |             |     | 0           |
|                     |      |     |               | Cost to Cure Ovr Comment        |             |     |             |

| BUILDING SUB-AREA SUMMARY SECTION |             |             |            |           |           |                 |  |
|-----------------------------------|-------------|-------------|------------|-----------|-----------|-----------------|--|
| Code                              | Description | Living Area | Gross Area | Eff. Area | Unit Cost | Undeprec. Value |  |
| BMT                               | BASEMENT    | 0           | 912        |           | 17.30     | 15,778          |  |
| FFL                               | 1ST FLOOR   | 1,152       | 1,152      |           | 86.69     | 99,870          |  |
| TQS                               | 3/4 STORY   | 684         | 912        |           | 65.02     | 59,298          |  |
| WDK                               | WOOD DECK   | 0           | 112        |           | 12.38     | 1,387           |  |
| Ttl. Gross Liv/Lease Area:        |             | 1,836       | 3,088      | 2,034     |           | 176,333         |  |

