

Print Date: 12/15/2017 10:45

VISION


CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	12		MULTI-CONV	#Heat Sys	1		
Model	03		MULTI-FAMILY	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	2.5			Int vs Ext	S		SAME
Foundation	3		MASONRY				
Exterior Wall 1	2		CLAPBOARD				
Exterior Wall 2							
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2							
Interior Floor 1	2		SOFTWOOD				
Interior Floor 2							
Heat Fuel	2		GAS				
Heat Type	3		FORCED H/W				
AC Type	03		FULL				
Bedrooms	4						
Full Baths	2						
Half Baths	0						
Extra Fixtures	0						
Total Rooms	8						
Bath Style	A		AVERAGE				
Kitchen Style	A		AVERAGE				
Kitchens	2						
Extra Kitchens	0						
Frame	1		WOOD				
Basement Floor							
Bsmt Garage							
Units	2						
WS Flues							
FBM Quality							
Fireplaces	0						

MIXED USE

Code	Description	Percentage
104	TWO FAM	100

COST/MARKET VALUATION

Adj. Base Rate:	81.52
Replace Cost	218,148
AYB	1900
EYB	1974
Dep Code	AV
Remodel Rating	
Year Remodeled	
Dep %	43
Functional Obslnc	
External Obslnc	
Cost Trend Factor	1
Condition	
% Complete	
Overall % Cond	57
Apprais Val	124,300
Dep % Ovr	0
Dep Ovr Comment	
Misc Imp Ovr	0
Misc Imp Ovr Comment	
Cost to Cure Ovr	0
Cost to Cure Ovr Comment	



OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
ATC	ATTIC	208	832		20.38	16,956
BMT	BASEMENT	0	1,196		16.29	19,483
EFP	ENCL PORCH	0	80		24.46	1,956
FFL	1ST FLOOR	1,336	1,336		81.52	108,911
OFP	OPEN PORCH	0	368		8.20	3,016
SFL	2ND FLOOR	832	832		81.52	67,825

Ttl. Gross Liv/Lease Area: 2,376 4,644 2,676 218,148

