

Print Date: 12/15/2017 19:31

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C+		AVG. (+)	FBM Sqft	421			
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				96.71
Interior Floor 1	3		HARDWOOD	Replace Cost				249,114
Interior Floor 2				AYB				1961
Heat Fuel	2		GAS	EYB				1987
Heat Type	1		FORCED H/A	Dep Code				GD
AC Type	03		FULL	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	3			Dep %				30
Half Baths	0			Functional ObsInc				
Extra Fixtures	0			External ObsInc				
Total Rooms	7			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				70
Extra Kitchens	0			Apprais Val				174,400
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	1			Cost to Cure Ovr Comment				
Fireplaces	1							

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	1,402		19.31	27,078	
EFP	ENCL PORCH	0	140		29.01	4,062	
FFL	1ST FLOOR	1,402	1,402		96.71	135,581	
GAR	GARAGE	0	308		38.62	11,895	
PAT	PATIO	0	135		5.01	677	
TQS	3/4 STORY	722	962		72.58	69,822	
Ttl. Gross Liv/Lease Area:		2,124	4,349	2,576		249,114	

