


CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.50		1 1/2 STORIES	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				109.61
Interior Floor 1	3		HARDWOOD	Replace Cost				174,825
Interior Floor 2				AYB				1954
Heat Fuel	2		GAS	EYB				1988
Heat Type	1		FORCED H/A	Dep Code				GD
AC Type	03		FULL	Remodel Rating				
Bedrooms	4			Year Remodeled				
Full Baths	1			Dep %				30
Half Baths	0			Functional Obslnc				
Extra Fixtures	1			External Obslnc				
Total Rooms	7			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				70
Extra Kitchens	0			Apprais Val				122,400
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality				Cost to Cure Ovr Comment				
Fireplaces	1							



BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	912		21.87	19,949	
EFP	ENCL PORCH	0	96		33.11	3,179	
FFL	1ST FLOOR	912	912		109.61	99,963	
HST	HALF STORY	456	912		54.80	49,981	
PAT	PATIO	0	320		5.48	1,754	
Ttl. Gross Liv/Lease Area:		1,368	3,152	1,595		174,825	