

# VISION

| CONSTRUCTION DETAIL |      |     |             | CONSTRUCTION DETAIL (CONTINUED) |             |     |             |
|---------------------|------|-----|-------------|---------------------------------|-------------|-----|-------------|
| Element             | Cd.  | Ch. | Description | Element                         | Cd.         | Ch. | Description |
| Style               | 19   |     | RANCH       | #Heat Sys                       | 1           |     |             |
| Model               | 01   |     | RESIDENTIAL | Central Vac                     | 0           |     | NO          |
| Grade               | C    |     | AVERAGE     | FBM Sqft                        |             |     |             |
| Stories             | 1.00 |     | 1 STORY     | Int vs Ext                      | S           |     | SAME        |
| Foundation          | 1    |     | CONCRETE    | MIXED USE                       |             |     |             |
| Exterior Wall 1     | 8    |     | BRICK VENR  | Code                            | Description |     | Percentage  |
| Exterior Wall 2     |      |     |             | 101                             | ONE FAM     |     | 100         |
| Roof Structure      | 4    |     | FLAT        |                                 |             |     |             |
| Roof Cover          | 1    |     | ASPHALT SH  |                                 |             |     |             |
| Interior Wall 1     | 1    |     | DRYWALL     |                                 |             |     |             |
| Interior Wall 2     | 8    |     | PLYWD PANL  | COST/MARKET VALUATION           |             |     |             |
| Interior Floor 1    | 4    |     | CARPET      | Adj. Base Rate:                 |             |     | 107.24      |
| Interior Floor 2    |      |     |             |                                 |             |     |             |
| Heat Fuel           | 2    |     | GAS         | Replace Cost                    |             |     | 164,826     |
| Heat Type           | 3    |     | FORCED H/W  | AYB                             |             |     | 1960        |
| AC Type             | 01   |     | NONE        | EYB                             |             |     | 1975        |
| Bedrooms            | 1    |     |             | Dep Code                        |             |     | AV          |
| Full Baths          | 1    |     |             | Remodel Rating                  |             |     |             |
| Half Baths          | 1    |     |             | Year Remodeled                  |             |     |             |
| Extra Fixtures      | 0    |     |             | Dep %                           |             |     | 43          |
| Total Rooms         | 4    |     |             | Functional Obslnc               |             |     |             |
| Bath Style          | A    |     | AVERAGE     | External Obslnc                 |             |     |             |
| Kitchen Style       | A    |     | AVERAGE     | Cost Trend Factor               |             |     | 1           |
| Kitchens            | 1    |     |             | Condition                       |             |     |             |
| Extra Kitchens      | 0    |     |             | % Complete                      |             |     |             |
| Frame               | 1    |     | WOOD        | Overall % Cond                  |             |     | 57          |
| Basement Floor      | 12   |     | CONCRETE    | Apprais Val                     |             |     | 94,000      |
| Bsmt Garage         |      |     |             | Dep % Ovr                       |             |     | 0           |
| Units               | 1    |     |             | Dep Ovr Comment                 |             |     |             |
| WS Flues            |      |     |             | Misc Imp Ovr                    |             |     | 0           |
| FBM Quality         |      |     |             | Misc Imp Ovr Comment            |             |     |             |
| Fireplaces          | 1    |     |             | Cost to Cure Ovr                |             |     | 0           |
|                     |      |     |             | Cost to Cure Ovr Comment        |             |     |             |

| BUILDING SUB-AREA SUMMARY SECTION |             |  |             |            |           |           |                 |  |  |  |  |  |
|-----------------------------------|-------------|--|-------------|------------|-----------|-----------|-----------------|--|--|--|--|--|
| Code                              | Description |  | Living Area | Gross Area | Eff. Area | Unit Cost | Undeprec. Value |  |  |  |  |  |
| BMT                               | BASEMENT    |  | 0           | 400        |           | 21.45     | 8,579           |  |  |  |  |  |
| FFL                               | 1ST FLOOR   |  | 1,450       | 1,450      |           | 107.24    | 155,496         |  |  |  |  |  |
| PAT                               | PATIO       |  | 0           | 140        |           | 5.36      | 751             |  |  |  |  |  |

| BUILDING SUB-AREA SUMMARY SECTION |             |  |             |            |           |           |                 |  |  |  |  |  |
|-----------------------------------|-------------|--|-------------|------------|-----------|-----------|-----------------|--|--|--|--|--|
| Code                              | Description |  | Living Area | Gross Area | Eff. Area | Unit Cost | Undeprec. Value |  |  |  |  |  |
| BMT                               | BASEMENT    |  | 0           | 400        |           | 21.45     | 8,579           |  |  |  |  |  |
| FFL                               | 1ST FLOOR   |  | 1,450       | 1,450      |           | 107.24    | 155,496         |  |  |  |  |  |
| PAT                               | PATIO       |  | 0           | 140        |           | 5.36      | 751             |  |  |  |  |  |

| BUILDING SUB-AREA SUMMARY SECTION |             |  |             |            |           |           |                 |  |  |  |  |  |
|-----------------------------------|-------------|--|-------------|------------|-----------|-----------|-----------------|--|--|--|--|--|
| Code                              | Description |  | Living Area | Gross Area | Eff. Area | Unit Cost | Undeprec. Value |  |  |  |  |  |
| BMT                               | BASEMENT    |  | 0           | 400        |           | 21.45     | 8,579           |  |  |  |  |  |
| FFL                               | 1ST FLOOR   |  | 1,450       | 1,450      |           | 107.24    | 155,496         |  |  |  |  |  |
| PAT                               | PATIO       |  | 0           | 140        |           | 5.36      | 751             |  |  |  |  |  |

| BUILDING SUB-AREA SUMMARY SECTION |             |  |             |            |           |           |                 |  |  |  |  |  |
|-----------------------------------|-------------|--|-------------|------------|-----------|-----------|-----------------|--|--|--|--|--|
| Code                              | Description |  | Living Area | Gross Area | Eff. Area | Unit Cost | Undeprec. Value |  |  |  |  |  |
| BMT                               | BASEMENT    |  | 0           | 400        |           | 21.45     | 8,579           |  |  |  |  |  |
| FFL                               | 1ST FLOOR   |  | 1,450       | 1,450      |           | 107.24    | 155,496         |  |  |  |  |  |
| PAT                               | PATIO       |  | 0           | 140        |           | 5.36      | 751             |  |  |  |  |  |

