

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	1		YES
Grade	C		AVERAGE	FBM Sqft	549		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	4		CARPET	Adj. Base Rate:		94.52	
Interior Floor 2							
Heat Fuel	2		GAS	Replace Cost		258,699	
Heat Type	3		FORCED H/W	AYB		1986	
AC Type	03		FULL	EYB		1999	
Bedrooms	4			Dep Code		GD	
Full Baths	2			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	1			Dep %		19	
Total Rooms	7			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		81	
Basement Floor	12		CONCRETE	Apprais Val		209,500	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	1			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	140	7.48	1986	A		AV	60	600

BUILDING SUB-AREA SUMMARY SECTION												
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value						
BMT	BASEMENT	0	1,098		18.94	20,794						
EFP	ENCL PORCH	0	168		28.13	4,726						
FFL	1ST FLOOR	1,098	1,098		94.52	103,782						
GAR	GARAGE	0	528		37.77	19,944						
SFL	2ND FLOOR	1,158	1,158		94.52	109,453						
Ttl. Gross Liv/Lease Area:		2,256	4,050	2,737		258,699						

