

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	1		YES
Grade	C+		AVG. (+)	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL	COST/MARKET VALUATION			
Interior Wall 2							
Interior Floor 1	4		CARPET	Adj. Base Rate:		101.46	
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost		283,976	
Heat Type	1		FORCED H/A	AYB		1985	
AC Type	03		FULL	EYB		1999	
Bedrooms	4			Dep Code		GD	
Full Baths	2			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	0			Dep %		19	
Total Rooms	8			Functional Obslnc			
Bath Style	G		GOOD	External Obslnc			
Kitchen Style	G		GOOD	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		81	
Basement Floor	12			Apprais Val		230,000	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality				Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

[illegible]

BUILDING SUB-AREA SUMMARY SECTION

<i>Code</i>	<i>Description</i>	<i>Living Area</i>	<i>Gross Area</i>	<i>Eff. Area</i>	<i>Unit Cost</i>	<i>Undeprec. Value</i>
BMT	BASEMENT	0	1,172		20.26	23,741
FFL	1ST FLOOR	1,317	1,317		101.46	133,618
GAR	GARAGE	0	580		40.58	23,538
OFP	OPEN PORCH	0	163		9.96	1,623
SFL	2ND FLOOR	918	918		101.46	93,137
WDK	WOOD DECK	0	585		14.22	8,319

[illegible]