


CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	06		COLONIAL	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft	354			
Stories	2.00		2 STORY	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				108.85
Interior Floor 1	3		HARDWOOD	Replace Cost				184,829
Interior Floor 2	4		CARPET	AYB				1994
Heat Fuel	2		GAS	EYB				2004
Heat Type	1		FORCED H/A	Dep Code				GD
AC Type	03		FULL	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	1			Dep %				14
Half Baths	1			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	7			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				86
Extra Kitchens	0			Apprais Val				159,000
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	3			Cost to Cure Ovr Comment				
Fireplaces	0							

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	708		21.83	15,457	
FFL	1ST FLOOR	848	848		108.85	92,306	
SFL	2ND FLOOR	708	708		108.85	77,067	

Ttl. Gross Liv/Lease Area:		1,556	2,264	1,698	184,829		
----------------------------	--	-------	-------	-------	---------	--	--



2007 10 15