

- Old hydrant #212 removed on 7-13-20  
New Waterous 250 hydrant installed 5-26-20. 67' west of old hydrant. Year built – 2020, 5-1/4" valve opening, bury – 5-1/2', 16' from hydrant to hydrant gate.
- Old hydrant #1004 removed  
New Waterous 250 hydrant installed 5-20-20. 39' east of old hydrant. Year built – 2019, 5-1/4" valve opening, bury – 6', 17'-3" from hydrant to hydrant gate.
- Old hydrant #184 removed on 6-23-20  
New Waterous 250 hydrant installed on 6-30-20. 72' west of old hydrant. Year built – 2019, 5-1/4" valve opening, bury – 6', 13'-6" from hydrant to hydrant gate.
- Old hydrant #1005 removed on 6-23-20  
New Waterous 250 hydrant installed 7-1-20. 20' west of old hydrant. Year built – 2019, 5-1/4" valve opening, bury – 6', 15' from hydrant to valve.
- Old hydrant #793 removed  
New Waterous 250 hydrant installed 7-9-20. 5' east of old hydrant. Year built – 2019, 5-1/4" valve opening, bury 6', 15' from hydrant to hydrant gate.
- Old hydrant #772 removed on 7-9-20 and new Waterous 250 hydrant located in same place. Year built – 2019, 5-1/4" valve opening, bury -6', 12'-10" from hydrant to hydrant gate.
- Note: hydrants 769 and 185 are existing hydrants that are off of the 12" AC main so we left them as is.