

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	545		
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	3			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	1		WOOD SHING	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2	1		DRYWALL	COST/MARKET VALUATION			
Interior Floor 1	2		SOFTWOOD	Adj. Base Rate:		73.28	
Interior Floor 2	12		CONCRETE				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost		245,619	
AC Type	03		FULL	AYB		1750	
Bedrooms	2			EYB		1945	
Full Baths	2			Dep Code		PR	
Half Baths	0			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	5			Dep %		69	
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc		5	
Kitchens	1			Cost Trend Factor		1	
Extra Kitchens	0			Condition		NC	
Frame	1		WOOD	% Complete		26	
Basement Floor				Overall % Cond		26	
Bsmt Garage				Apprais Val		63,900	
Units	1			Dep % Ovr		0	
WS Flues	1			Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr		0	
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	144	7.48	1981	A		FR	50	500
40	LEAN-TO			L	112	5.75	1981	A		AV	60	400

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
ATC	ATTIC	14	56		18.32	1,026	
BMT	BASEMENT	0	779		14.67	11,431	
FFL	1ST FLOOR	2,041	2,041		73.28	149,555	
HST	HALF STORY	162	323		36.75	11,871	
OPF	OPEN PORCH	0	84		6.98	586	
PAT	PATIO	0	60		3.66	220	
SFL	2ND FLOOR	968	968		73.28	70,931	
Ttl. Gross Liv/Lease Area:		3,185	4,311	3,352		245,619	

