

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	02		BUNGALOW	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	746		
Stories	1.5			Int vs Ext	S		
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	2		CLAPBOARD	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		87.96	
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost		140,304	
Heat Type	5		STEAM	AYB		1910	
AC Type	03		FULL	EYB		1975	
Bedrooms	2			Dep Code		AV	
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %		39	
Total Rooms	5			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		61	
Basement Floor	12			Apprais Val		85,600	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues	1			Misc Imp Ovr		0	
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
03	GARAGE	OB	Outbuilding	L	420	28.18	1930	A		AV	60	7,100

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
ATC	ATTIC	267	1,066		22.03	23,487	
BMT	BASEMENT	0	1,066		17.58	18,737	
FFL	1ST FLOOR	1,092	1,092		87.96	96,058	
OFP	OPEN PORCH	0	226		8.95	2,023	
Ttl. Gross Liv/Lease Area:		1,359	3,450	1,595		140,304	

