

Print Date: 12/27/2014 20:54

VISION

CONSTRUCTION DETAIL						CONSTRUCTION DETAIL (CONTINUED)						
Element	Cd.	Ch.	Description			Element	Cd.	Ch.	Description			
Style	19		RANCH			#Heat Sys	1					
Model	01		RESIDENTIAL			Central Vac	0					
Grade	C		AVERAGE			FBM Sqft	874					
Stories	1.00		1 Story			Int vs Ext	S					
Foundation	1					MIXED USE						
Exterior Wall 1	4		VINYL			Code	Description			Percentage		
Exterior Wall 2						101	ONE FAM			100		
Roof Structure	1		GABLE									
Roof Cover	1		ASPHALT SH									
Interior Wall 1	1		DRYWALL									
Interior Wall 2						COST/MARKET VALUATION						
Interior Floor 1	3		HARDWOOD			Adj. Base Rate:			109.17			
Interior Floor 2												
Heat Fuel	1		OIL			Replace Cost			167,903			
Heat Type	1		FORCED H/A			AYB			1952			
AC Type	03		Full			EYB			1975			
Bedrooms	3					Dep Code			AV			
Full Baths	1					Remodel Rating						
Half Baths	1					Year Remodeled						
Extra Fixtures	0					Dep %			39			
Total Rooms	6					Functional Obslnc						
Bath Style	A		AVERAGE			External Obslnc						
Kitchen Style	A		AVERAGE			Cost Trend Factor			1			
Kitchens	1					Condition						
Extra Kitchens	0					% Complete						
Frame	1		WOOD			Overall % Cond			61			
Basement Floor	12					Apprais Val			102,400			
Bsmt Garage	1					Dep % Ovr			0			
Units	1					Dep Ovr Comment						
WS Flues	1					Misc Imp Ovr			0			
FBM Quality	3					Misc Imp Ovr Comment						
Fireplaces	2					Cost to Cure Ovr			0			
OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
BUILDING SUB-AREA SUMMARY SECTION												
Code	Description			Living Area		Gross Area	Eff. Area		Unit Cost		Undeprec. Value	
BMT	BASEMENT			0		1,248			21.87		27,292	
FFL	1ST FLOOR			1,248		1,248			109.17		136,244	
WDK	WOOD DECK			0		288			15.16		4,367	
Ttl. Gross Liv/Lease Area:				1,248		2,784	1,538				167,903	

