

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	1		YES
Grade	C+		AVG. (+)	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		88.62	
Interior Floor 2							
Heat Fuel	2		GAS	Replace Cost		246,017	
Heat Type	1		FORCED H/A	AYB		2011	
AC Type	03		FULL	EYB		2012	
Bedrooms	3			Dep Code		GD	
Full Baths	2			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	2			Dep %		2	
Total Rooms	7			Functional Obslnc			
Bath Style	G		GOOD	External Obslnc			
Kitchen Style	G		GOOD	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		98	
Basement Floor	12			Apprais Val		241,100	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality				Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	1,240		17.72	21,978	
FFL	1ST FLOOR	1,247	1,247		88.62	110,513	
GAR	GARAGE	0	624		35.51	22,156	
OFP	OPEN PORCH	0	106		9.20	975	
SFL	2ND FLOOR	1,020	1,020		88.62	90,395	

Ttl. Gross Liv/Lease Area:		2,267	4,237	2,776		246,017	
----------------------------	--	-------	-------	-------	--	---------	--

