

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	06		COLONIAL	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft	564			
Stories	2.00		2 Story	Int vs Ext	S			
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				86.56
Interior Floor 1	3		HARDWOOD	Replace Cost				199,271
Interior Floor 2	4		CARPET	AYB				2006
Heat Fuel	2		GAS	EYB				2010
Heat Type	1		FORCED H/A	Dep Code				GD
AC Type	03		FULL	Remodel Rating				
Bedrooms	4			Year Remodeled				
Full Baths	2			Dep %				4
Half Baths	0			Functional Obslnc				
Extra Fixtures	1			External Obslnc				
Total Rooms	7			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				96
Extra Kitchens	0			Apprais Val				191,300
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12			Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	3			Cost to Cure Ovr Comment				
Fireplaces	1							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
020822	SHED/FR POOL A-O WOOD DK			L	160	7.48	2009	A		GD	70	800
				L	33	69.00	2013	A		GD	70	1,600
				L	112	9.20	2013	A		GD	70	700

Ttl. Gross Liv/Lease Area:		1,968	3,541	2,302		199,271
----------------------------	--	-------	-------	-------	--	---------

