

VISION

CONSTRUCTION DETAIL			CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NONE
Grade	C		AVERAGE	FBM Sqft	246		
Stories	1.00		1 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	2		HIP				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			103.40
Interior Floor 2							
Heat Fuel	1		OIL				
Heat Type	3		FORCED H/W	Replace Cost			149,311
AC Type	03		Full	AYB			1957
Bedrooms	3			EYB			1987
Full Baths	1			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	5			Dep %			27
Bath Style	A		AVERAGE	Functional ObsInc			
Kitchen Style	A		AVERAGE	External ObsInc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor				Overall % Cond			73
Bsmt Garage				Apprais Val			109,000
Units	1			Dep % Ovr			0
WS Flues	1			Dep Ovr Comment			
FBM Quality	1			Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
19	PATIO			L	100	5.75	1989	A		GD	70	400

BUILDING SUB-AREA SUMMARY SECTION									
--	--	--	--	--	--	--	--	--	--

<i>Code</i>	<i>Description</i>	<i>Living Area</i>	<i>Gross Area</i>	<i>Eff. Area</i>	<i>Unit Cost</i>	<i>Undeprec. Value</i>
BMT	BASEMENT	0	492		20.60	10,133
FFL	1ST FLOOR	1,192	1,192		103.40	123,254
GAR	GARAGE	0	384		41.47	15,924

--	--	--	--	--	--	--

