

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	1		
Grade	B+		GOOD (+)	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	8		BRICK VENR	Code	Description		Percentage
Exterior Wall 2	2		CLAPBOARD	101	ONE FAM		100
Roof Structure	2		HIP				
Roof Cover	2		SLATE				
Interior Wall 1	1		DRYWALL	COST/MARKET VALUATION			
Interior Wall 2				Adj. Base Rate:			95.40
Interior Floor 1	3		HARDWOOD				
Interior Floor 2							
Heat Fuel	2		GAS	Replace Cost			338,098
Heat Type	1		FORCED H/A	AYB			1995
AC Type	03		Full	EYB			2004
Bedrooms	3			Dep Code			GD
Full Baths	3			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	2			Dep %			10
Total Rooms	7			Functional ObsInc			
Bath Style	G		GOOD	External ObsInc			
Kitchen Style	G		GOOD	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			90
Basement Floor	12			Apprais Val			304,300
Bsmt Garage				Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality				Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

[illegible]

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,608		19.10	30,719
FFL	1ST FLOOR	1,608	1,608		95.40	153,403
GAR	GARAGE	0	675		38.16	25,758
OFP	OPEN PORCH	0	70		9.54	668
SFL	2ND FLOOR	1,134	1,134		95.40	108,184
UAT	UNFIN ATTC	0	1,017		19.04	19,366
Ttl. Gross Liv/Lease Area:		2,742	6,112	3,544		338,098

