

CURRENT OWNER				TOPO.				UTILITIES				STRT./ROAD				LOCATION				CURRENT ASSESSMENT									
ALBEN TIMOTHY P ALBEN MARYANN 40 HERITAGE CR EAST LONGMEADOW, MA 01028 Additional Owners:								1 TYPCL												Description		Code		Appraised Value		Assessed Value		1006 AST LONGMEADOW, M 	

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	06		COLONIAL	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	1		YES	
Grade	B-		GOOD (-)	FBM Sqft	1265			
Stories	2.00		2 Story	Int vs Ext	S			
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				90.98
Interior Floor 1	3		HARDWOOD	Replace Cost				362,636
Interior Floor 2	4		CARPET	AYB				1993
Heat Fuel	2		GAS	EYB				2003
Heat Type	1		FORCED H/A	Dep Code				GD
AC Type	03		FULL	Remodel Rating				
Bedrooms	4			Year Remodeled				
Full Baths	3			Dep %				11
Half Baths	1			Functional Obslnc				
Extra Fixtures	3			External Obslnc				
Total Rooms	8			Cost Trend Factor				1
Bath Style	G		GOOD	Condition				
Kitchen Style	G		GOOD	% Complete				
Kitchens	1			Overall % Cond				89
Extra Kitchens	0			Apprais Val				322,700
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12			Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	4			Cost to Cure Ovr Comment				
Fireplaces	1							

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	2,108		18.21	38,392	
FFL	1ST FLOOR	2,108	2,108		90.98	191,780	
GAR	GARAGE	0	506		36.32	18,377	
OFP	OPEN PORCH	0	656		9.15	6,005	
SFL	2ND FLOOR	1,160	1,160		90.98	105,534	
WDK	WOOD DECK	0	200		12.74	2,547	
Ttl. Gross Liv/Lease Area:		3,268	6,738	3,986		362,636	

