

Print Date: 12/28/2014 11:14

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.75		1 3/4 Stories	Int vs Ext	S			
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	2		PLASTER					
Interior Wall 2								
Interior Floor 1	3		HARDWOOD					
Interior Floor 2	1		PLYWOOD	Adj. Base Rate:				89.81
Heat Fuel	1		OIL	Replace Cost				168,125
Heat Type	1		FORCED H/A	AYB				1950
AC Type	01		NONE	EYB				1975
Bedrooms	4			Dep Code				AV
Full Baths	2			Remodel Rating				
Half Baths	0			Year Remodeled				
Extra Fixtures	1			Dep %				39
Total Rooms	6			Functional Obslnc				
Bath Style	A		AVERAGE	External Obslnc				
Kitchen Style	A		AVERAGE	Cost Trend Factor				1
Kitchens	1			Condition				
Extra Kitchens	0			% Complete				
Frame	1		WOOD	Overall % Cond				61
Basement Floor	12			Apprais Val				102,600
Bsmt Garage	1			Dep % Ovr				0
Units	1			Dep Ovr Comment				
WS Flues				Misc Imp Ovr				0
FBM Quality				Misc Imp Ovr Comment				
Fireplaces	1			Cost to Cure Ovr				0
				Cost to Cure Ovr Comment				

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
40	LEAN-TO			L	104	5.75	1975	A		AV	60	400

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	960		17.96	17,244	
FFL	1ST FLOOR	960	960		89.81	86,218	
TQS	3/4 STORY	720	960		67.36	64,663	
Ttl. Gross Liv/Lease Area:		1,680	2,880	1,872		168,125	

TQS	40
FFL	
BMT	
24	24
40	

