

Print Date: 12/28/2014 11:19

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	437		
Stories	1.00		1 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	3		ALUMINUM	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2	1		DRYWALL	COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		83.42	
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost		164,763	
Heat Type	3		FORCED H/W	AYB		1955	
AC Type	01		NONE	EYB		1975	
Bedrooms	3			Dep Code		AV	
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %		39	
Total Rooms	6			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		61	
Basement Floor	12			Apprais Val		100,500	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	1			Misc Imp Ovr Comment			
Fireplaces	0			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

Ttl. Gross Liv/Lease Area:		1,456	3,553	1,975	164,763	
----------------------------	--	-------	-------	-------	---------	--

