

Print Date: 12/28/2014 12:47

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		
Grade	C		AVERAGE	FBM Sqft	221		
Stories	1.50		1 1/2 Stories	Int vs Ext	S		
Foundation	2			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		97.72	
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost		146,880	
Heat Type	1		FORCED H/A	AYB		1945	
AC Type	03		Full	EYB		1980	
Bedrooms	3			Dep Code		AG	
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %		34	
Total Rooms	6			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		66	
Basement Floor	12			Apprais Val		96,900	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
03	GARAGE	OB	Outbuilding	L	294	28.18	1958	A		GD	70	5,800

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	884		19.57	17,297	
FFL	1ST FLOOR	884	884		97.72	86,389	
HST	HALF STORY	442	884		48.86	43,194	
Ttl. Gross Liv/Lease Area:		1,326	2,652	1,503		146,880	

HST	34
FFL	
BMT	
26	26
	34

