

Print Date: 12/28/2014 14:18

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.75		1 3/4 Stories	Int vs Ext	S			
Foundation	1			MIXED USE				
Exterior Wall 1	3		ALUMINUM	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2								
Interior Floor 1	3		HARDWOOD					
Interior Floor 2				Adj. Base Rate:				86.79
Heat Fuel	1		OIL	Replace Cost				166,730
Heat Type	3		FORCED H/W	AYB				1949
AC Type	01		NONE	EYB				1980
Bedrooms	4			Dep Code				AG
Full Baths	1			Remodel Rating				
Half Baths	1			Year Remodeled				
Extra Fixtures	1			Dep %				34
Total Rooms	7			Functional Obslnc				
Bath Style	A		AVERAGE	External Obslnc				
Kitchen Style	A		AVERAGE	Cost Trend Factor				1
Kitchens	1			Condition				
Extra Kitchens	0			% Complete				
Frame	1		WOOD	Overall % Cond				66
Basement Floor	12			Apprais Val				110,000
Bsmt Garage				Dep % Ovr				0
Units	1			Dep Ovr Comment				
WS Flues				Misc Imp Ovr				0
FBM Quality				Misc Imp Ovr Comment				
Fireplaces	1			Cost to Cure Ovr				0
				Cost to Cure Ovr Comment				

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	912		17.32	15,796
EFP	ENCL PORCH	0	124		25.90	3,211
FFL	1ST FLOOR	912	912		86.79	79,155
GAR	GARAGE	0	264		34.85	9,200
TQS	3/4 STORY	684	912		65.09	59,367

Ttl. Gross Liv/Lease Area: 1,596 3,124 1,921 166,730

