

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C+		AVG. (+)	FBM Sqft	329		
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			91.79
Interior Floor 2							
Heat Fuel	1		OIL				
Heat Type	3		FORCED H/W	Replace Cost			215,978
AC Type	01		NONE	AYB			1965
Bedrooms	4			EYB			1988
Full Baths	2			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	8			Dep %			26
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond			74
Bsmt Garage				Apprais Val			159,800
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	1			Misc Imp Ovr			0
Fireplaces	2			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	1,096		18.34	20,102	
FFL	1ST FLOOR	1,096	1,096		91.79	100,600	
GAR	GARAGE	0	440		36.72	16,155	
OFP	OPEN PORCH	0	120		9.18	1,101	
SFL	2ND FLOOR	850	850		91.79	78,020	
Ttl. Gross Liv/Lease Area:		1,946	3,602	2,353		215,978	

