

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		
Grade	B		GOOD	FBM Sqft	572		
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			102.11
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost			275,097
Heat Type	1		FORCED H/A	AYB			1981
AC Type	03		Full	EYB			1996
Bedrooms	4			Dep Code			GD
Full Baths	2			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	1			Dep %			18
Total Rooms	7			Functional Obslnc			
Bath Style	G		GOOD	External Obslnc			
Kitchen Style	G		GOOD	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			82
Basement Floor				Apprais Val			225,600
Bsmt Garage				Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,144		20.44	23,384
FFL	1ST FLOOR	1,174	1,174		102.11	119,883
GAR	GARAGE	0	506		40.77	20,627
OPF	OPEN PORCH	0	64		9.57	613
SFL	2ND FLOOR	1,036	1,036		102.11	105,791
WDK	WOOD DECK	0	336		14.28	4,799
Ttl. Gross Liv/Lease Area:		2,210	4,260	2,694		275,097

