

Print Date: 12/29/2014 09:12

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		
Grade	C+		AVG. (+)	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1						
Exterior Wall 1	4		VINYL				
Exterior Wall 2							
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	4		CARPET				
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A				
AC Type	03		Full				
Bedrooms	3						
Full Baths	2						
Half Baths	1						
Extra Fixtures	2						
Total Rooms	8						
Bath Style	G		GOOD				
Kitchen Style	G		GOOD				
Kitchens	1						
Extra Kitchens	0						
Frame	1		WOOD				
Basement Floor	12						
Bsmt Garage							
Units	1						
WS Flues							
FBM Quality							
Fireplaces	1						

MIXED USE

Code	Description	Percentage
101	ONE FAM	100

COST/MARKET VALUATION

Adj. Base Rate:	85.50
Replace Cost	260,352
AYB	2001
EYB	2007
Dep Code	GD
Remodel Rating	
Year Remodeled	
Dep %	7
Functional Obslnc	
External Obslnc	
Cost Trend Factor	1
Condition	
% Complete	
Overall % Cond	93
Apprais Val	242,100
Dep % Ovr	0
Dep Ovr Comment	
Misc Imp Ovr	0
Misc Imp Ovr Comment	
Cost to Cure Ovr	0
Cost to Cure Ovr Comment	

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
19	PATIO			L	144	5.75	2003	G		GD	70	700
02	SHED/FR			L	160	7.48	2004	G		GD	70	1,000

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,208		17.13	20,691
FFL	1ST FLOOR	1,208	1,208		85.50	103,286
GAR	GARAGE	0	576		34.14	19,665
HST	HALF STORY	252	504		42.75	21,546
SFL	2ND FLOOR	1,028	1,028		85.50	87,896
TQS	3/4 STORY	54	72		64.13	4,617
WDK	WOOD DECK	0	224		11.83	2,651

Ttl. Gross Liv/Lease Area: 2,542 4,820 3,045 260,352

