

Print Date: 11/25/2015 11:11

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	15		OLD STYLE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	2.00		2 Story	Int vs Ext	S			
Foundation	3			MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				81.56
Interior Floor 1	3		HARDWOOD	Replace Cost				128,783
Interior Floor 2	4		CARPET	AYB				1910
Heat Fuel	2		GAS	EYB				2002
Heat Type	1		FORCED H/A	Dep Code				GD
AC Type	03		FULL	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	2			Dep %				12
Half Baths	0			Functional Obslnc				
Extra Fixtures	0			External Obslnc				5
Total Rooms	6			Cost Trend Factor				1
Bath Style	G		GOOD	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				83
Extra Kitchens	0			Apprais Val				106,900
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12			Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality				Cost to Cure Ovr Comment				
Fireplaces	1							

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	96	7.48	2007	A		GD	70	500

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	728		16.36	11,908
FFL	1ST FLOOR	728	728		81.56	59,376
SFL	2ND FLOOR	368	368		81.56	30,014
TQS	3/4 STORY	270	360		61.17	22,021
WDK	WOOD DECK	0	480		11.38	5,465
Ttl. Gross Liv/Lease Area:		1,366	2,664	1,579		128,783

