

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft	134			
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME	
Foundation	2		CONC BLOCK	MIXED USE				
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	2		PLASTER					
Interior Wall 2	8		PLYWD PANL	Adj. Base Rate:				94.84
Interior Floor 1	3		HARDWOOD	Replace Cost				149,278
Interior Floor 2	4		CARPET	AYB				1954
Heat Fuel	2		GAS	EYB				1975
Heat Type	1		FORCED H/A	Dep Code				AV
AC Type	01		NONE	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	1			Dep %				39
Half Baths	1			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	7			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				61
Extra Kitchens	0			Apprais Val				91,100
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	1			Cost to Cure Ovr Comment				
Fireplaces	1							

BUILDING SUB-AREA SUMMARY SECTION												
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value						
BMT	BASEMENT	0	672		18.91	12,709						
EFP	ENCL PORCH	0	48		27.66	1,328						
FFL	1ST FLOOR	792	792		94.84	75,113						
GAR	GARAGE	0	240		37.94	9,105						
TQS	3/4 STORY	504	672		71.13	47,799						
WDK	WOOD DECK	0	240		13.44	3,225						
Ttl. Gross Liv/Lease Area:		1,296	2,664	1,574			149,278					

