

Vision ID: 2520

Account #2563

Bldg #: 1 of 1

Sec #: 1 of

1 Card 1 of 1

Print Date: 11/25/2015 15:03

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	2		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	1080		
Stories	1.00		1 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			83.68
Interior Floor 2							
Heat Fuel	2		GAS				
Heat Type	3		FORCED H/W				
AC Type	01		NONE	Replace Cost	217,233		
Bedrooms	5			AYB	1978		
Full Baths	2			EYB	1990		
Half Baths	0			Dep Code	AG		
Extra Fixtures	1			Remodel Rating			
Total Rooms	8			Year Remodeled			
Bath Style	A		AVERAGE	Dep %	24		
Kitchen Style	A		AVERAGE	Functional Obslnc			
Kitchens	1			External Obslnc			
Extra Kitchens	0			Cost Trend Factor	1		
Frame	1		WOOD	Condition			
Basement Floor	12			% Complete			
Bsmt Garage				Overall % Cond	76		
Units	1			Apprais Val	165,100		
WS Flues				Dep % Ovr	0		
FBM Quality	3			Dep Ovr Comment			
Fireplaces	1			Misc Imp Ovr	0		
				Misc Imp Ovr Comment			
				Cost to Cure Ovr	0		
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	80	7.48	2008	A		GD	70	400

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,200		16.74	20,083
FFL	1ST FLOOR	1,525	1,525		83.68	127,612
SFL	2ND FLOOR	800	800		83.68	66,944
WDK	WOOD DECK	0	220		11.79	2,594
Ttl. Gross Liv/Lease Area:		2,325	3,745	2,596		217,233

