

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		
Grade	C		AVERAGE	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL	COST/MARKET VALUATION			
Interior Wall 2				Adj. Base Rate:		81.24	
Interior Floor 1	4		CARPET				
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost		204,076	
AC Type	03		Full	AYB		1994	
Bedrooms	4			EYB		2003	
Full Baths	2			Dep Code		GD	
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	7			Dep %		11	
Bath Style	A		AVERAGE	Functional ObsInc			
Kitchen Style	A		AVERAGE	External ObsInc			
Kitchens	1			Cost Trend Factor		1	
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond		89	
Bsmt Garage				Apprais Val		181,600	
Units	1			Dep % Ovr		0	
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr		0	
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

[illegible]

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	988		16.28	16,086
FFL	1ST FLOOR	988	988		81.24	80,266
GAR	GARAGE	0	576		32.44	18,685
PAT	PATIO	0	280		4.06	1,137
SFL	2ND FLOOR	1,064	1,064		81.24	86,440
WDK	WOOD DECK	0	132		11.08	1,462

Ttl. Gross Liv/Lease Area:		2,052	4,028	2,512		204,076

PAT[280]

